



24 Waterway , Suite 1450
The Woodlands, TX 77380
Tel: (281) 210-1170

September 18, 2008

Symbol: TSX-V: PBR

PROBE ANNOUNCES OPERATIONAL UPDATE

Probe Resources Ltd. (the “Company” or “Probe”) is pleased to provide an update on its operations in the aftermath of Hurricanes Gustav and Ike.

High Island 115 (41.5% WI, 30.9% NRI)

The Operator of the High Island 115 Platform inspected the facility on September 15, 2008 and reported minor damage from the hurricanes. Assessment of the host platform at HI 71 is underway by its operator. The departing export line and onshore separation facility have not reported significant damage. Production from the well is expected to resume within the next two weeks.

East Cameron 36 (100% WI, 69.5% NRI)

A caisson was driven over the well and a nav-aid package was installed prior to Hurricane Ike. The rig was evacuated on September 10 and crews returned on September 16. No damage was found to either the rig or the caisson. The rig was released on September 16. First production from the well is expected in late fourth quarter 2008 after installation of a test separator deck on the caisson and a pipeline to a nearby host facility. It should also be noted that no damage was found to the host facility.

East Cameron 246 (100% WI, 70% NRI)

The Company spud its East Cameron 246 well on September 6, 2008. The rig was evacuated on September 10 for Hurricane Ike. Crews returned to the rig on September 16. The well sustained limited damage as a result of the hurricane. The Company is currently evaluating the damage and believes that the well will be delayed by approximately one week as result of repair operations. The Company is insured for the cost of damage to the well. The Company’s share of the cost (the insurance deductible) will not have a significant impact on the total cost of the drilling and completion of the well.

South Timbalier 214 (100% WI, 70% NRI)

The Company’s South Timbalier 198 platform, which is intended as the drill site for the South Timbalier 214 well, had no significant damage as result of the hurricanes. The expected spud date has been delayed to mid-October as a result of the evacuations from the rig slated for use on the well. This rig is currently contracted to another operator.

About Probe Resources Ltd.

The Company, along with its wholly owned subsidiary Probe Resources US Ltd. located in The Woodlands, Texas, is an oil and natural gas exploration and production company focused on generating, acquiring, developing, and operating drilling prospects within the Texas and Louisiana Outer Continental Shelf of the Gulf of Mexico.

For further information, please contact:

Scott Broussard, Chief Executive Officer and Chairman of the Board

Telephone: (281) 210-1170

E-mail: sbroussard@probe-resources.com

Or visit our website at www.probe-resources.com

ON BEHALF OF PROBE RESOURCES LTD.

“Scott Broussard”

Chief Executive Officer and Chairman of the Board

This news release does not constitute an offer to sell or a solicitation of an offer to buy any of the Company's securities in the United States. The Company's securities have not been and will not be registered under the United States Securities Act of 1933, as amended (the "U.S. Securities Act") or any state securities laws and may not be offered or sold within the United States or to U.S. persons unless registered under the U.S. Securities Act and applicable state securities laws or an exemption from such registration is available.

Statements in this press release may contain forward-looking information including expectations of future operations (including drill rig commitments and use of proceeds), commerciality of any gas discovered, operating costs, commodity prices, administrative costs, commodity price risk management activity, acquisitions and dispositions, capital spending, access to credit facilities, income and oil taxes, regulatory changes, and other components of cash flow and earnings. The reader is cautioned that assumptions used in the preparation of such information may prove to be incorrect. Events or circumstances may cause actual results to differ materially from those predicted, a result of numerous known and unknown risks, uncertainties, and other factors, many of which are beyond the control of the Company. These risks include, but are not limited to, the risks associated with the oil and gas industry, commodity prices and exchange rate changes. Industry related risks could include, but are not limited to, operational risks in exploration, development and production, delays or changes in plans, risks associated to the uncertainty of reserve estimates, or reservoir performance, health and safety risks and the uncertainty of estimates and projections of production, costs and expenses. The reader is cautioned not to place undue reliance on this forward-looking information.

The TSX Venture Exchange does not accept responsibility for the adequacy or accuracy of this release.